

FOOTWEAR CONTENT LABELING GUIDE for EU COUNTRIES

1. Requirement Disclose material content of specified components.
2. Coverage All footwear.
3. Components Upper, lining, sock and outersole.
4. Tolerance 80% of surface area of upper, lining or sock; 80% of volume (weight?) of outersole.
5. Method of Disclosure Printing, sticking, embossing or labeling.
6. Disclosure Requirements Visible, securely attached and accessible. Symbols acceptable.
7. Materials Leather (includes all forms except leather with a coating greater than .15mm), coated leather, textile, all other materials (includes composition leather).
8. Bonded Leather Would be disclosed as other materials.

9. The EU symbols are as follows:

		Leather	
Upper		Coated leather	
Lining and sock		Natural textile materials and synthetic or non woven textile materials	
Outer sole		All other materials	